

1. Disconnect everything to turn everything off
  - Power off both computers
  - Unplug KVM switch (disconnect small black plug on the far far right of the KVM)
  - Unplug the monitor (big black box to the right of the screen)
2. Power up only the monitor
3. A blue light should appear on the bottom and a BARCO logo appears
4. Wait
5. The logo will go away and the light will turn orange
6. Press the hidden buttons on the panel (to the left of the orange light)
7. You will hear clicking and the buttons will light up
8. Press the grid looking button, if a menu appears on the screen you are ok, more then likely nothing will appear on the screen
  - If nothing appears on the screen this is your problem
9. Press the power button on the screen (You are turning the screen off but leaving it plugged in)
10. Orange light will appear and screen will be dark
11. Press the power button on the screen (to turn it back on)
12. Press the grid button to see if a menu appears, if the menu appears (a grey and red menu) the screen is fixed
  - If a grid doesnt appear, repeat steps 9-12
13. Plug in the KVM (Black box for switching between computers)
14. Turn on computers

\* If the orange light starts blinking during steps 13-14 its ok.